

PRODUCT ADVISORY NOTICE

KEEPING YOU INFORMED OF PRODUCT CHANGES

To: Sales Representatives and Distributors
Date: 04/28/2025
Subject: 68B change to lubricant and application process

Please forward this notification to the appropriate person(s) in your organization.

Description of Change

Grayhill is changing the lubricant used on the 68B series and the process for applying it during manufacturing.

The lubricant is in the same family as the previous, but it has a slightly higher viscosity for better ability to remain in place over the life of the product.

The manufacturing process is changing to apply the lubricant more efficiently.

Reason for Change

The changes are designed to improve the quality of the product, resulting in quieter operation. The new lubricant has been tested to meet the 2M cycle rating for product life.

Effective Date

Production orders after March 25, 2025 will begin transitioning to the new lubricant and method.

Part Numbers Affected

All standard 68B part numbers; 68BY001, 68BY002, 68BY008, 68BY014, 68BY015, 68BY022, 68BY023, 68BY031, 68BY034, 68BY039, 68BY040, 68BY041, 68BY043, 68BY044, 68BY047, 68BY048, 68BY049, 68BY052, 68BY053, 68BY054, 68BY057

Action Required

Please contact your Grayhill, Inc. Sales Area Leader for further information.

###