

# PRODUCT ADVISORY NOTICE

---

KEEPING YOU INFORMED OF PRODUCT CHANGES

---

**To:** All Customers, Sales Representatives and Distributors

**Date:** May 14, 2014

**Subject:** Select tact switch cover/support plating material change

This Product Advisory Notice is to alert you that Grayhill is changing the material on the cover/support of the 95 Series right angle through-hole tact switches. Samples have been made using the new material and have passed our qualification testing.

## **Description of Change**

Grayhill is changing the plating of the cover/support from a current plating at 100 microinches of Tin to a cover/support plating of 4 microinches of Silver over 100 microinches of Nickel.

## **Reason for Change**

This change is part of a Grayhill Tin whisker mitigation strategy.

## **Effective Date**

Immediately

## **Part Numbers Affected**

95C06A2RAT  
95C06A3RAT  
95C06A4RAT  
95C06B2RAT  
95C06B3RAT  
95C06B4RAT  
95C06C2RAT  
95C06C3RAT  
95C06C4RAT  
95C06D2RAT  
95C06D3RAT  
95C06D4RAT  
95C06E2RAT  
95C06E3RAT  
95C06E4RAT  
95C06F2RAT  
95C06F3RAT  
95C06F4RAT

## **Action Required**

Please forward this notification and the test report to the appropriate person(s) in your organization. If the change is acceptable, no action is necessary. If you would like to request a copy of the test reports, receive a free sample or have questions, contact your Grayhill, Inc. sales associate.

